



m\*8  
M6\*16

c\*8

i\*1

j\*1



Lx2 Nx2 Px1


step1.

m\*8  
M6\*16


c\*8

i\*1


j\*1




step2.



a*6  M6*30	b*4  M6*50	c*12 	d*6 	f*2  Φ 13 (M6) *4mm	g*12 	h*6 	i*1 	j*1 
--	---	---	--	--	--	--	--	--




step1.



step2.

a*6  M6*30	c*6 	g*6 	i*1 	
---	--	--	--	--



step3.



c\*2



d\*2



g\*2





h\*2








i\*1




j\*1







step4.




step5.






x2




A x2	B x2	C x2	D x4
E x4	F x2	G x2	


step1.




step2.







x2



step3.



step4.



step5.

x2

